

SOUTHERN WATER SERVICES LIMITED

121884



120718

438159

438108

LEGEND - MAINS		MATERIALS	
	Clockwise closing valve		Alkathene
	Fire Hydrant		Cast iron
	Washout		Open (grey) iron
	Washout hydrant		Concrete
	Meter		Ductile iron
	Capped end		Banded Asbestos Cement
	Emptying plug		Glass reinforced plastic
	Stopcock		Glass reinforced epoxy
	Leak Noise Correlator Survey Point		(Ethylacrylate) Polyvinyl chloride
	Anode		Polyethylene
	Telermity cable		PVC
	Access point / Hubbox		PE
			SI
			CSB
			CSU
			GI
			DS
			CSF
			HPE
			??

O.S. Ref. SU3721SW
 Drawn by: kumaria
 Scale: 1:2500
 Date: 05/04/2019
 Title: U1430652_Land at Halterworth

The positions of pipes shown on this plan are believed to be correct, but Southern Water Services Ltd accept no responsibility in the event of inaccuracy. The actual position of pipes must be determined on site.
 WARNING: BAC pipes are constructed of Banded Asbestos Cement
 WARNING: Unknown (UNK) materials may include Banded Asbestos Cement
 Based upon Ordnance Survey Digital Data with the permission of the Controller of H.M.S.O. Crown Copyright Reserved Licence No. WU298530

